


ALAMANCE-BURLINGTON SCHOOL SYSTEM 10.13.20


CUMMINGS HIGH SCHOOL ADDITION AND RENOVATIONS






- SECURITY VESTIBULE RENOVATION
- ARTS CLASSROOMS RENOVATIONS
- MUSIC HALL LOBBY ADDITION
 - AUDITOIRUM RENOVATION
- BAND ROOM RENOVATION
- CHORAL ROOM RENOVATION
 - TECHNOLOGY UPGRADES

ENTRANCE RENOVATION



ENTRANCE RENOVATION






SCOPE ELEMENTS


GROUP TOILET RENOVATIONS

- WINDOW/DOOR REPLACEMENT
- SECURITY VESTIBULE RENOVATION
- ARTS CLASSROOMS RENOVATIONS
- MUSIC HALL LOBBY ADDITION
 - AUDITOIRUM RENOVATION
- BAND ROOM RENOVATION
- CHORAL ROOM RENOVATION
 - TECHNOLOGY UPGRADES


ART ROOMS RENOVATIONS




ART ROOMS RENOVATIONS




DANCE ROOM RENOVATION



DANCE ROOM RENOVATION







SCOPE ELEMENTS


- GROUP TOILET RENOVATIONS
- WINDOW/DOOR REPLACEMENT
- SECURITY VESTIBULE RENOVATION
- ARTS CLASSROOMS RENOVATIONS
- MUSIC HALL LOBBY ADDITION
 - AUDITOIRUM RENOVATION
- BAND ROOM RENOVATION
- CHORAL ROOM RENOVATION
 - TECHNOLOGY UPGRADES

BAND ROOM RENOVATION




CHORAL AND ENSEMBLE RENOVATION





LOBBY ADDITION



LOBBY ADDITION

